

**D-Motor International bvba**

Houtekiestraat 11

B-8540 Deerlijk, Belgium

Tel. +32 56 49 81 49

[Info@d-motor.eu](mailto:Info@d-motor.eu)**SERVICE BULLETIN D-MOTOR**

Service Bulletin NO. 2019-012

**SUBJECT** : Product changes spark plugs / spark plug covers**MODELS AFFECTED** : All models**TIME OF COMPLIANCE** : from prod date 01/03/2019**AFFECTED SERIAL NUMBER(S)** : All engines from serial number LF2619001 and LF3919001

An ECO (Engineering Change Order) has been issued for the Spark plug covers and the spark plugs.

**Spark Plugs**

The Beru spark plugs type UXT are changed into the Z121 model due to better performance and availability.

The Beru spark plugs, installed before compliance date, are NOT to be changed, but can be changed.



Service Bulletin 2019 - 012							
ISSUED			REVISED			Pages	Rev.
Day	Month	Year	Day	Month	Year		
01	03	2019				2	1

## Spark plug Covers

The NGK spark plug covers type      are changed into the type LB05-F.

These covers have better contact with the new Beru Z121 spark plugs. The Spark plug covers installed before the time of compliance are NOT to be changed but CAN be changed.



Resistor value : 5 K Ohm

M4 connection

Angle : 90°

Service Bulletin 2019 - 012							
ISSUED			REVISED			Pages	Rev.
Day	Month	Year	Day	Month	Year	2	1
01	03	2019					